Questions & Answers **Dvorak Services** COMM # 54228-9777-01-A BRRTS # 03-36-172363

To what extent is possible groundwater migration and vapors in adjacent Question:

utility corridors to be investigated.

Utility corridors that intersect the ground water plume are to be identified and appropriate manhole covers are to be removed and air monitoring is Answer:

to be conducted.